


Examples of the cracks which have occurred after the foundation work was done.



Bowing brace in attic.



Floor tile coming up/ crack.



High grading, broken corner brick.